



# PERRY'S

## TENTS & EVENTS

550 S. OLD TELEGRAPH RD.

PONTIAC, MI 48341

PH. (248) 334-1577 FAX (248) 334-3370 [perrystentsandevents.com](http://perrystentsandevents.com)



## OPERATING INSTRUCTIONS



# SAFETY PRECAUTIONS

Paragon values your continued safety above all else. Please follow these guidelines when using your equipment to prevent injury and maximize product performance:



Always wear safety glasses when servicing equipment.

---




Shaver reaches high speeds during operation. To avoid injury, NEVER place body parts or objects such as ice picks into or near the shaver head assembly while motor is running. *Paragon is not responsible for any injuries that may occur due to failure to follow safety precautions.*

---



Any alterations made to equipment by anyone other than certified Paragon personnel will void warranty and may also create unsafe working conditions. NEVER make alterations to the equipment.

---



Machine must be properly grounded to prevent electrical shock. Do NOT immerse any other part of this equipment in water. Doing so may damage equipment and prevent it from working properly. Always unplug equipment before cleaning or servicing to prevent electric shock.

---

**UNIT TO BE OPERATED BY RESPONSIBLE  
ADULT(S) ONLY !!!**

**!!!DO NOT LET CHILDREN OPERATE !!!!!!!!!!!**

## OPERATING INSTRUCTIONS

Be sure equipment is connected to properly grounded 120 volt power supply with 15 amp circuit. (230 volts for export models)

### Shaving Ice

1. Turn POWER switch ON (Not used on The Cooler and The Arctic Blast).
2. Fill the ice horn with ice.
3. Press and hold the MOTOR switch to activate blades and begin shaving ice.
4. While holding MOTOR switch down, apply steady downward pressure to the ice pusher
5. Release the MOTOR switch when finished.
6. Repeat steps 2-5 for additional batches.

**BLADES ARE SHARP AND OPERATE AT HIGH SPEEDS!** Please be sure to keep all body parts and any objects such as picks or scoops away from the ice horn while POWER is on!